



US1000 Developer board



uneven pull-up / down arrangement to enable the use of active data bus for buttons



US1000 Developer board - PRELIMINARY
P. Lehtonen / ULSI Solution Oy 2007

TITLE: vs1000_devel_rev04



Document Number:

REV:
0.4

Date: 10/22/2007 13:59:44

Sheet: 1/2

PSU & Power Button



Test Pins

Sheet: 2/2